

Fig. 1




Fig. 2

2

CMC EMULATOR

CMC REPORTS

PMA

DATA LOADER

LRU SOFTWARE

AIR DATA
AIR GROUND
SIMULATION

PRINT
OPTION

AIRLINE
SOFTWARE
APPLICATION

File Edit View Options Notes Bookmarks IR's Window Help

ATA#

Close

ToC

Search

GoBack

FitCode

EICAS

Equip

36210

BLEED-1 HIGH PRESSURE CONTROLLER/HPSOV FAIL CLOSED

CORRECTIVE ACTION:

NOTE: If <READ SNAPSHOT shows, push the adjacent LSK to see a maintenance snapshot related to the problem.

A. Replace the Engine No. 1 High Pressure Controller, M7191 ().

B. If the problem still exist, do these corrective actions listed in order of probability:

- (1) Replace the Engine No. 1 High Pressure Shutoff Valve, V347 ().
- (2) Examine the Engine No. 1 HPSOV/HPC signal pressure tube for leaks.
- (3) Examine the Engine No. 1 HPC supply pressure tube for leaks.
- (4) Examine the Engine No. 1 HPC enable solenoid wiring for an open circuit (WDM 36-11-41).
- (5) Replace the ASCTU, M7957 ().
- (6) Examine the Engine No. 1 HPC PHL switch wiring for a short (WDM 36-11-41).
- (7) Examine the Engine No. 1 HPSOV closed switch wiring for a short (WDM 36-11-41).
- (8) Examine the Engine No. 1 HPC closed solenoid wiring for a short (WDM 36-11-41).

BLEED HP ENG 1 (STATUS)

BLEED HP ENG 1 (ADVISORY)

3

36211

BLEED-2 HIGH PRESSURE CONTROLLER/HPSOV FAIL CLOSED

CORRECTIVE ACTION:

NOTE: If <READ SNAPSHOT shows, push the adjacent LSK to see a maintenance snapshot related to the problem.

A. Replace the Engine No. 2 High Pressure Controller, M7191 ().

B. If the problem still exist, do these corrective actions listed in order of probability:

- (1) Replace the Engine No. 2 High Pressure Shutoff Valve, V347 ().

BLEED HP ENG 2 (STATUS)

BLEED HP ENG 2 (ADVISORY)

Effectivity: ALL

36-00-00-0, Uncontrolled Document. For Reference Only.

Fig. 3

CMC EMULATOR	CMC REPORTS	PMA	DATA LOADER	LRU SOFTWARE	AIR DATA AIR/GROUND SIMULATION	PRINT OPTION	AIRLINE SOFTWARE APPLICATION
<p>PRESENT LEG FAULTS SUMMARY REPORT PAGE 1</p> <p>VR-HOY 881 RCTP/VHHH 685-2270-010 CMC-L RR-012 29MAR97 0227</p>							
<p>WINDOW HEAT 1R - STATUS: 30 40 04 00 A</p>							
<p>AC BUS 2 NOT POWERED 29MAR97 0203 ATA: 24-11 EQUIP: POWER ON MSG: 24701</p>							
<p>WINDOW HEAT 1L - STATUS: 30 40 03 00 A</p>							
<p>AC BUS 4 NOT POWERED 29MAR97 0203 ATA: 24-11 EQUIP: POWER ON MSG: 24703</p>							
<p>BLEED HP ENG 1 - STATUS: 36 10 35 00 A</p>							
<p>BLEED-1 HIGH PRESSURE 28MAR97 2213 ATA: 36-11 CONTROLLER/HPSOV CRUISE FAIL CLOSED MSG: 36210</p>							

Fig. 4




Fig. 5

ONBOARD PRINTER



CMC EMULATOR	CMC REPORTS	PMA	DATA LOADER	LRU SOFTWARE	AIR DATA AIR/GROUND SIMULATION	PRINT OPTION	AIRLINE SOFTWARE APPLICATION
<div> <div>File Edit View Options Notes Bookmarks IR's Window Help</div> <div> Close Toc Search GoBack FitCode WMsg# EICAS Equip ATA# </div> </div> <div> <div>36210</div> <div>BLEED-1 HIGH PRESSURE CONTROLLER/HPSOV FAIL CLOSED</div> <div> <div>BLEED HP ENG 1</div> <div>BLEED HP ENG 1</div> <div>(STATUS)</div> <div>(ADVISORY)</div> </div> </div> <div>CORRECTIVE ACTION:</div> <div> <div>NOTE: If <READ SNAPSHOT shows, push the adjacent LSK to see a maintenance snapshot related to the problem.</div> <div> <div>A. Replace the Engine No. 1 High Pressure Controller, M7191 (AMM 36-11-06/401).</div> <div> <div>B. If the problem still exist, do these corrective actions listed in order of probability:</div> <div> <div>(1) Replace the Engine No. 1 High Pressure Shutoff Valve, V347 (AMM 36-11-05/401).</div> <div>(2) Examine the Engine No. 1 HPSOV/HPC signal pressure tube for leaks.</div> <div>(3) Examine the Engine No. 1 HPC supply pressure tube for leaks.</div> <div>(4) Examine the Engine No. 1 HPC enable solenoid wiring for an open circuit (WDM 36-11-41).</div> <div>(5) Replace the ASCTU, M7957 (AMM 36-11-30/401).</div> <div>(6) Examine the Engine No. 1 HPC PHL switch for a short (WDM 36-11-41).</div> <div>(7) Examine the Engine No. 1 HPSOV closed switch wiring for a short (WDM 36-11-41).</div> <div>(8) Examine the Engine No. 1 HPC closed solenoid wiring for a short (WDM 36-11-41).</div> </div> </div> </div> <div>CMCS Message</div> <div>BLEED-2 HIGH PRESSURE CONTROLLER/HPSOV FAIL CLOSED</div> <div> <div>Possible Flight Deck Effect</div> <div>BLEED HP ENG 2</div> <div>BLEED HP ENG 2</div> <div>(STATUS)</div> <div>(ADVISORY)</div> </div> </div> <div>CORRECTIVE ACTION:</div> <div> <div>NOTE: If <READ SNAPSHOT shows, push the adjacent LSK to see a maintenance snapshot related to the problem.</div> <div> <div>A. Replace the Engine No. 2 High Pressure Controller, M7191 (AMM 36-11-06/401).</div> <div> <div>B. If the problem still exist, do these corrective actions listed in order of probability:</div> <div> <div>(1) Replace the Engine No. 2 High Pressure Shutoff Valve, V347 (AMM 36-11-05/401).</div> </div> </div> </div> </div>							

Fig. 6

Effectivity: ALL

36-00-00-0, Uncontrolled Document. For Reference Only.